



Harvester Guard inspection certificate

# New Holland 440FI

#23170-20

Industriestraat 23  
5961 PH Horst  
The Netherlands  
T + 31 (0)77 - 2066603  
sales@ammachinery.nl  
<https://test.ammachinery.nl/>



Dear sir/madame,

Thank you for your interest in our **New Holland 440FI** built in ,with our internal stock number **23170-20**.We are a dedicated SPFH specialist, we work professional and transparent, all our equipment is cleaned and run trough our 200 points inspection report. Use this link to get below information:

<https://test.ammachinery.nl/new-holland-440fi-23170-20.html>

## Technical specifications

Partnumber	23170-20	Brand	New Holland
Model	440FI		

## Options

## 2) Short Description

---

New Holland 440FI\_23170-20

## Description

---

2009 New Holland 440FI 8 row rotary corn header. This header has been inspected and is good working.

## 3) Product Images

---